


### EXPLANATION

- ★ Sample site
- ▼ Fault trace
- ♂ Spring
- △ Base station
- ▩ Steep scarp
- ▨ Gentle scarp
- ▧ Deep scarp
- ▦ Shallow scarp
- ⚡ Crack, < .5 m deep
- Soil mound
- Piezometer
- Tr Buried tree
- - - Suspected Fault zone
- ▬ Open crack or Graben
- ⤵ Soil thrust toe deposit
- ▨ Ponded water
- ⋯ Ephemeral stream
- ⊖ Alluvial deposit
- ▬ Road
- Control point
- Tree raft



CONTOUR INTERVAL 5 METERS

Latitude, longitude, and elevation from GPS.  
 Field work conducted in 1996.



46°00'42" N

46°00'42" N